



MANUFACTURING SOLUTIONS, INC.

Model C3-A Chamfermate^R Minimum Recommended Spare Parts
for Machines with Standard 3" O.D. Head Only*

Qty	Part Number	Description	
1	M12010	Stop Rod Bushing	
1	11795	Stop Rod	
5	M10361	Insert Seat	
5	M10362	Insert Seat Screw	
2	M10359	Insert Clamp	
5	M10360	Insert Clamp Screw	
1	11400	Wedge	
1	M10602	Wedge Screw	
1	11399	Adjustment Screw	
1	M10757	Single Solenoid Valve	
1	M10255	Limit Switch	
1	M10006	Relay	
3	M12129	Motor Fuses (20A)	for 3HP, 240VAC machines
	M12079	Motor Fuses (10A)	for 3HP, 380-480VAC machines
	M12131	Motor Fuses (30A)	for 5HP, 240VAC machines
	M12916	Motor Fuses (15A)	for 5HP, 380-480VAC machines
1	M10725	Control Fuse	
1	M10774	Timing Belt	

Machines are Supplied with a 30 Degree OR a 45 Degree

1	12244	30 Degree Toolholder Assembly (If So Equipped)
1	12562	45 Degree Toolholder Assembly (If So Equipped)

Slide Stop Recommended Spare Parts if so Equipped

1	M10758	Double Solenoid Valve
---	--------	-----------------------

Manufacturing Solutions, Inc.
9485 College
Beaumont, TX 77707
800-831-1130 Fax 409-842-9445
www.msi-tx.com
Email: info@msi-tx.com